



Ford Connect

cable 912



If you can not read correctly, replace the 8 Mhz oscillator by a 4 Mhz for programming

